
| City of Baltimore Wet<br>Smoke and Dyed                                     | Page 1 of 1                  |  |
|---|------------------------------|--|
| Sewershed: Gwynns Falls   | Company: Savin               | Date: 9/30/2009                              |
| Test to be performed: Ground Condition:   Smoke Dyed Water X Dry ✓ Damp Wet |                              | Supervisor: JAW                              |
| Manhole_ID: S08K 004MH  | Test ID: <u>D1032-006005</u> | Notification Made: NA (Residents, Fire, 311) |

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



| Defect Loc  | Obs_ClockFrom | Obs_ClockTo | Observation        | Obs_Remarks                 |
|-------------|---------------|-------------|--------------------|-----------------------------|
| 0           |               |             | Start of Survey    |                             |
| 0           |               |             | Manhole            | S08K004MH                   |
| 0           |               |             | Water Level        |                             |
| 4           |               |             | Dye Test Visible   | LEAK AT THE JOINT           |
| 10.89999962 | 09            |             | Tap Factory Active | BELIEVE FLOW COMING FROM CB |
| 20.60000038 |               |             | Abandoned Survey   | DYE TEST IS COMPLETE        |